



MKII Truck Timer Software Issue

To : Recipient of this 12.016 Truck Timer

It has been found that some timers stop working in automatic mode after test button of cab light button is used to initiate a cycle. It will not resume automatic cycling until power is cut from both:

- #1 wire – ignition and
- #12 wire – battery

Please wire this unit with both #1 and #12 to ignition. This will insure that the timer will go into automatic mode upon turning the key off and on again, after the button has been pushed.

We are sending you this timer, as our stock levels are low. This is the only unit we can send at this time. We expect more timers Around Sept 20, 2010. We will gladly replace this timer with a new unit upon delivery of our next shipment of timers. We apologize for any inconvenience.

