




12.015 – LC Timer Connector Crimps

We've had reports of a loose connection on the main connector on the gray Lubecore timer (LCT Timer). For units installed between August 2011 and Oct 2011, please inspect for proper crimping and insertion of terminals. We ask that during your normal PM check, you pay special attention to this. Pushing the red button should result in the system doing a single cycle. Please do this as well as giving the connector a close look, and performing a quick physical check of the connections by giving each wire a tug to ensure proper crimp and insertion. Also, please ensure that timers are mounted where they will not be in harm's way, i.e. somewhere they won't be kicked and/or get wet.

12.015 – 10Vdc - 30Vdc Truck Timer



12.015 – 10Vdc - 30Vdc Truck Timer

Wire Connections

